

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

677
NE
1/2-1
0.985 mi.
5201 ft.

2411 EAST 3RD ST
2411 EAST 3RD ST
BROOKLYN, NY

NY Spills S104648649
N/A

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: 2411 EAST 3RD ST
Address: 2411 EAST 3RD ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9814440 / 2005-10-25
Facility ID: 9814440
Facility Type: ER
DER Facility ID: 230367
Site ID: 284064
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 1999-03-03
Investigator: GWBURKE
Referred To: Not reported
Reported to Dept: 1999-03-03
CID: 351
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-03-03
Spill Record Last Update: 2005-10-25
Spiller Name: GARY FLANANBAUM
Spiller Company: LEFRAK
Spiller Address: Not reported
Spiller Company: 001
Contact Name: TOM DERITA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was M
TIBBE SPOKE WITH JOHN GOODWIN OF MYSTIC, ABOUT 10 GLS. SPILLED ONTO
THE SIDEWALK DUE TO THE PIPING IN THE BUILDING BREAKING. JOHN FROM
MYSTIC SAID THEY WILL NOT BE RESPONDING TO THIS SPILL. HESS IS
ARRANGING THE CLEANUP. 12:55PM. 10/25/05 - Close less than 25 gallons
on sidewalk. Cleaned by HESS. GB"
Remarks: "DRIVER WAS THERE FILLING TANK AND THE UNDERGROUND PIPE LEADING TO
THE TANK BROKE"

All Materials:

Site ID: 284064
Operable Unit ID: 1075481
Operable Unit: 01
Material ID: 311127
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported